



**Underwriters
Laboratories Inc.®**

Northbrook Division
333 Pfingsten Road
Northbrook, IL 60062-2096 USA
www.ul.com
tel: 1 847 272 8800
fax: 1 847 272 8129
Customer service: 1 877 854 3577

NOTICE OF AUTHORIZATION TO APPLY THE UL MARK

2006-08-07

Mr. Roni Cohen
Hi-G-Tek Ltd
16 Hacharroshet St
Or-Yahuda,
Israel

E-mail: rcohen@higtek.com
Reference: File E256795 Project 06NK18748
Product(s): USL, CNL - Lock Datasel, Model IG-LK-40-XXX

Dear Mr. Cohen,

UL's investigation of your product has been completed under the above project number and the subject product was determined to comply with the applicable requirements.

This letter temporarily supplements the UL Follow-Up Services Procedure and serves as authorization to apply the UL Listing Mark only at the factory under UL's Follow-Up Service Program to the subject product(s), which is (are) constructed as described below:

Identical to the subject models, which were submitted to UL for this investigation. The UL Records covering the product will be in the Follow-Up Services Procedure, File E256795, Volume 1.

This authorization applies only to the address on this letter.

This authorization is effective from the date of this Notice and only for products at the indicated manufacturing locations. Records in the Follow-Up Services Procedure covering the product are now being prepared and will be sent to the indicated manufacturing locations in the near future. Please note that Follow-Up Services Procedures are sent to the manufacturers only unless the Applicant specifically requests this document.

Products that bear the UL Mark shall be identical to those that were evaluated by UL and found to comply with UL's requirements. If changes in construction are discovered, appropriate action will be taken for products not in conformance with UL's requirements and continued use of the UL Mark may be withdrawn.

Sincerely,

Joshua A. Saunders
Engineer
Hazardous Locations, Gas & Oil
Conformity Assessment Services
Tel: 847-664-3429
Fax: 847-313-3429
E-mail: joshua.saunders@us.ul.com

Reviewed by:

David P. Malohn
Staff Engineer
Hazardous Locations, Gas & Oil
Conformity Assessment Services
E-mail: david.p.malohn@us.ul.com

